File Original and First Copy with Department of Ecology Second Copy -- Owner's Copy Third Copy -- Driller's Copy

WATER WELL REPORT STATE OF WASHINGTON

Application No.

Permit No 61-221821

(1) OWNER: Name HILL TOP ASSOCIATES	Address 4208 N. 5. 195TRHT, A	ENT	D.V. WA
	5E% NEW Sec 144_ T.28		
Bearing and distance from section or subdivision corner 1420 South	THE I HO WEST FROM N. F. Comme	_	-1
(3) PROPOSED USE: Domestic Industrial Municipal Irrigation Test Well Other	(10) WELL LOG: (166' N \$ 166' W FF Formation: Describe by color, character, size of material show thickness of aquifers and the kind and nature of the	and stru	cture, and
(A) MYDE OF WORK. Owner's number of well	etratum penetratea, with at least one entry for each cit	FROM	TO
(4) TYPE OF WORK: Owner's number of well (if more than one)		. 0	30
Deepened	BROWN SAND	30	200
Reconditioned Rotary Jetted	BLUE CLAY & GRAVELWA	200	2.0H
(5) DIMENSIONS: Diameter of well inches. Drilled 219 ft. Depth of completed well 217 ft.	GRAY MED SAND HARD PACKED	204 217	217
(6) CONSTRUCTION DETAILS:			-
Casing installed: 6" Diam. from			
Threaded [] " Diam. from			
Welded W Th. to ft. to ft.			
Perforations: Yes No X			
Type of perforator usedin. byin.			
perforations from			
perforations from ft. to ft			ļ
perforations from It. W			
Screens: Yes A No []			
Manufacturer's Name John Son			
No. L Slot size 10 from 2/2 ft. to 2/7 ft.			
Diam. 6 Slot size 8 from 207 ft. to 212 ft.			
Gravel packed: Yes No Size of gravel:			
Gravel placed from ft. to ft.			
Surface seal: Yes No [] To what depth? ft.	'		
Material used in seal Stationite Did any strata contain unusable water? Yes No [3]		·	
Type of water? Depth of strate		·	
Method of sealing strate off		 	 -
(7) PUMP: Manufacturer's Name STA-RITE			
Type:		 	
(8) WATER LEVELS: Land-surface elevation above mean sea level	· 	 	+
Static level 128 ft. below top of well Date 10-2-51			
Artesian pressure ibs. per square inch Date: Artesian water is controlled by (Cap, valve, etc.)		1	
(9) WELL TESTS: Drawdown is amount water level is lowered below static level	Work started 10-11 1974 Completed 10	-21	D., 1974.
Was a pump test made? Yes W No I If yes, by whom? DRIALER.	WELL DRILLER'S STATEMENT:		`.
Yield: 10 gal/min. with 82 ft. drawdown after 4 nrs	This well was drilled under my jurisdiction	and thi	s report is
	true to the best of my knowledge and belief.		
December data: (time taken as zero when pump turned off) (water leve	i n $n > n$,	
Recovery data (time taken measured from well top to water level) Time Water Level Time Water Level Time Water Level	(Ferson, firm, or corporation)	Type or	•
	Address P.O. Box 55 FREEL	BAL	2 4/2
	. PHULIODS.		982

Date of testhr	(Well Dritter)		_
A design flow	"	-26	7, 19 <i>.74</i>
Temperature of water	<u> </u>	_	•